

Figure 13C. Typical Eave Detail for Purlin Roof System with 2X Blocking

