Figure 19A. Typical Roof Peak or Ridge Detail



Detail courtesy The Murus Company, Inc. · Reproduced by NorthEast SIPs with permis