


Figure 7A. Typical Inlet Nailer Connection Detail



Detail courtesy The Murus Company, Inc. · Reproduced by NorthEast SIPs with permission