




NOTE: FLOATING DRYWALL CORNERS ARE RECOMMENDED TO REDUCE POSSIBLE CORNER CRACKING



DETAIL: PANEL TO DIVISON WALL

SCALE: N.T.S.

UPDATED: 1/26/16

DETAIL#

DW1

ENERGY PANEL STRUCTURES, 102 EAST INDUSTRIAL PARK, GRAETTINGER, IA 51342
PHONE: (712) 859-3219 FAX: (712) 859-3275 WWW.EPSBUILDINGS.COM